Replacement Sheets 10/825,746, Group 3663 Sheet 1 of 14






Fig. 1A (Prior Art)

Fig. 1B (Prior Art)




Fig. 1C (Prior Art)




Fig. 1D (Prior Art)

Replacement Sheets 10/825, 746, 60mp 3683 sheet 3 of 14




Fig. 3A

Fig. 3B




Fig. 3C




Fig. 3D




Fig. 3E




Fig. 3F




Fig. 3G




Fig. 3H




Fig. 3I




Fig. 3J




Fig. 4A




Fig. 4B




Fig. 4C




Fig. 4D

Replacement sheets 10/825, 746, Group 3665 Sheet 10 of 14

Input to the EA modulator




Fig. 5A

Fig. 5B




Fig. 6A




Fig. 6B




Fig. 7A




Fig. 7B




Fig. 7C




Fig. 7D




Fig. 7E




Fig. 7F